

ATTACHMENT #18

**CAPRICORN\INTERNATIONAL ANNUAL
VEHICLE INSPECTIONS**

(7 Pages)

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 10/13/06, 16:48
Test Type: Initial
Test: Safety
Version Number: 0513
License Number: V5103537
Vehicle ID Number: 3CER8J22X55103537
Vehicle Make: Other
Vehicle Model: BUS
Vehicle Year: 2005
Vehicle Type: B
GVW:
Odometer/Fuel Type: 202152 / DIESEL

Station Identification

Station Name: H & H TRUCK REPAIR INC.
Station Number: 2P12833
Station Address: 122 ROSE LANE EAST
Station City: HOUSTON
Station Zip Code: 770760000
Inspector First Name: PHILLIP
Inspector Last Name: HUGHES
Analyzer Number: SE400021

Safety Inspection Fee: \$ 60.00
Safety Repair Costs: \$ 0.00

Total Inspection Cost: \$ 60.00

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U01672902

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.



Certified Inspector's Signature

8V5103537



3CER8J22X55103537



(2)

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 11/08/07, 12:50
Test Type: Initial
Test: Safety
Version Number: 0603
License Number: V5103537
Vehicle ID Number: 3CER8J22X55103537
Vehicle Make: Other
Vehicle Model: VOLVO
Vehicle Year: 2005
Vehicle Type: B
GVW:
Odometer/Fuel Type: 377324 / DIESEL

Station Identification

Station Name: H & H TRUCK REPAIR INC
Station #/Analyzer: 2P12833 / SE400021
Station Address: TDLS Reprint
Station City: N/A
Station Zip Code: N/A
Inspector First Name: PHILLIP
Inspector Last Name: HUGHES

| | | |
|------------------------|----|-------|
| Safety Inspection Fee: | \$ | 62.00 |
| Safety Repair Costs: | \$ | 0.00 |
| | | ----- |
| Total Inspection Cost: | \$ | 62.00 |

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U02115480

VI-30a Number: 13733757

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.

Certified Inspector's Signature

2V5103537



3CER8J22X55103537



(3)

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 11/06/07, 12:54
Test Type: Initial
Test: Safety
Version Number: 0603
License Number: V5120995
Vehicle ID Number: 3CER8G12385120995
Vehicle Make: Other
Vehicle Model: VOLVO
Vehicle Year: 2008
Vehicle Type: B
GVW:
Odometer/Fuel Type: 001737 / DIESEL

Station Identification

Station Name: H & H TRUCK REPAIR INC
Station #/Analyzer: 2P12833 / SE400021
Station Address: TDLS Reprint
Station City: N/A
Station Zip Code: N/A
Inspector First Name: ANA
Inspector Last Name: CHICAS

| | |
|------------------------|----------|
| Safety Inspection Fee: | \$ 62.00 |
| Safety Repair Costs: | \$ 0.00 |
| | ----- |
| Total Inspection Cost: | \$ 62.00 |

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U02115469

VI-30a Number: 13733755

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.

Certified Inspector's Signature

2V5120995



3CER8G12385120995



4

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 11/06/07, 12:01
Test Type: Initial
Test: Safety
Version Number: 0603
License Number: V5101425
Vehicle ID Number: 3CES5J12655101425
Vehicle Make: Other
Vehicle Model: VOLVO BUS
Vehicle Year: 2005
Vehicle Type: T
GVW: 52000
Odometer/Fuel Type: 375848 / DIESEL

Station Identification

Station Name: H & H TRUCK REPAIR INC
Station #/Analyzer: 2P12833 / SE400021
Station Address: TDLS Reprint
Station City: N/A
Station Zip Code: N/A
Inspector First Name: ANA
Inspector Last Name: CHICAS

| | | |
|------------------------|----|-------|
| Safety Inspection Fee: | \$ | 62.00 |
| Safety Repair Costs: | \$ | 0.00 |
| | | ----- |
| Total Inspection Cost: | \$ | 62.00 |

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U02115467

VI-30a Number: 13733754

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.

Certified Inspector's Signature

2V5101425



3CES5J12655101425



5

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 11/05/07, 16:30
Test Type: Initial
Test: Safety
Version Number: 0603
License Number: V5101398
Vehicle ID Number: 3CES5J12755101398
Vehicle Make: Other
Vehicle Model: VOLVO
Vehicle Year: 2005
Vehicle Type: B
GVW:
Odometer/Fuel Type: 373306 / DIESEL

Station Identification

Station Name: H & H TRUCK REPAIR INC
Station #/Analyzer: 2P12833 / SE400021
Station Address: TDLS Reprint
Station City: N/A
Station Zip Code: N/A
Inspector First Name: ANA
Inspector Last Name: CHICAS

| | |
|------------------------|----------|
| Safety Inspection Fee: | \$ 62.00 |
| Safety Repair Costs: | \$ 0.00 |
| | ----- |
| Total Inspection Cost: | \$ 62.00 |

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U02115465

VI-30a Number: 13733753

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.

Certified Inspector's Signature

2V5101398



3CES5J12755101398



(6)

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

Vehicle Identification

Test Date/Time: 11/10/07, 16:03
Test Type: Initial
Test: Safety
Version Number: 0509
License Number: V5120994
Vehicle ID Number: 3CER8G12185120994
Vehicle Make: Other
Vehicle Model: BUS
Vehicle Year: 2008
Vehicle Type: B
GVW: 48000
Odometer/Fuel Type: 000000 / DIESEL

Station Identification

Station Name: 5 MINUTES INSPECTIONS
Station #/Analyzer: 2P35798 / WW610130
Station Address: TDLS Reprint
Station City: N/A
Station Zip Code: N/A
Inspector First Name: CESAR
Inspector Last Name: HERNANDEZ

| | | |
|------------------------|----|-------|
| Safety Inspection Fee: | \$ | 62.00 |
| Safety Repair Costs: | \$ | 0.00 |
| ----- | | |
| Total Inspection Cost: | \$ | 62.00 |

Safety Test Results

Safety Sequence: F.M.C.S.R. VEHICLES

All Items Passed

Gas Cap Integrity:

Safety Items: Pass

Overall Result: Pass

Certificate Number: U02036028

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.

I certify that I have properly performed the safety test according to applicable rules and regulations.

Certified Inspector's Signature

2V5120994



3CER8G12185120994



(7)